

LLANFAIR CAEREINION TOWN COUNCIL**WEEKLY INSPECTION SHEETS****DATD 24th December 2025**

REF	HEADING	DETAILS	STATUS
1	MOUNT FIELD	GRASS CUTTING	
2		FENCES AND GATES	
3		BINS	
4		RAILINGS	
5		BUILDINGS	
6		STANDS	
7		CAR PARK	
8		CONTAINERS	
9	ST MARY'S CHURCH	GRASS CUTTINGS	
10		GRAVESTONES	
11		LIGHTING	
12		LYCHGATE	
13		WALLS	
14		ELECTRICAL BOXES	
15		PATHS	
16		FLAGPOLES	
17	WAR MEMORIAL		
18	DERI WOODS/GOAT FIELD	PATHS AND BRIDGES	
19		FENCES AND GATES	
20		WHITE BRIDGE	
21		TREES	
22		STEPS	
23		DOG POO DISPENSERS	
24		PUMP HOUSE	
25		CAR PARK	
26		BENCHES AND SEATING	
27		PIG PEN	
28		SCUPTURE	
29	ERW DDWR	GRASS CUTTING	
30		HEDGES	
31		FENCES AND GATES	
32		ENTRANCE AREA	
33		GRAVESTONES	
34		RUBBISH BINS	
35	TOILETS	BUILDING EXTERNAL	
36		BUILDING INTERNAL GENTS	
37		BUILDING INTERNAL LADIES	
38		BUILDING INTERNAL DISABLED	
39		PATHS	

40		CERTIFICATES	
41		CLEANING	
42	CHAPEL OF REST	BUILDING EXTERNAL	
43		BUILDING INTERNAL	
44		GARDENS	
45		FENCES AND GATES	
46		CERTIFICATES	
47		COOLING UNIT	
48	PLAYGROUND	GRASS CUTTING	
49		FENCES AND GATES	
50		RETAINING WALLS (TIMBER)	
50		BINS	
51		SEATING	
52		LARGE SLIDE	
53		SMALL SLIDE	
54		CLIMBING FRAME	
55		GAMES UNIT	
56		ROUNDAABOUT	
57		BOUNCERS	
58		INFANT SWINGS	
59		JUNIOR SWINGS	
60		FITNESS TRAIL	
61	TENNIS COURTS	SURFACE	
62		NETS AND POSTS	
63		FENCES AND GATTES	
64		BINS	
65		SEATING	
66		GRASSED AREAS	
67	BOWLING CLUB	BUILDINGS	
68		GREEN	
69		BOUNDARY HEDGES	
70		CAR PARK AND ACCESS	
71	STREET SCENE	OUTSIDE FISH AND CHIP SHOP	
72		SIGNPOSTS	
73		BENCHES	
74		BINS	
75		TOWN TRAIL	
76		MAP BOARDS	
77		TELEPHONE BOX WATERGATE ST	
78		TELEPHONE BOX HIGH STREET	
79	DEFIBRILLATORS	CROWN HOUSE	
80		BLACK LION	
81		MOUNT FIELD	
82		Rhiweniath village hall	

83		WATERGATE STREET
84		THE INSTITUTE
85	COUNCIL OFFICES	OFFICE EQUIPMENT
86		BUILDING INTERNAL
87		CHRISTMAS LIGHTS
88	PARC ONNEN	GATES
89		VERGES
90	RIVERSIDE WALK	PATH



NOTES

Liners checked

Wall by chapel monitored.

Resurfacing required.

Restocked

side gate needs repairs to post.

4 posts bottom fence need repair.

Timber edging needs repair.

Needs strimming.