

LLANFAIR CAEREINION TOWN COUNCIL

INSPECTION REPORT

DATED - 30th November 2025

CARRIED OUT BY R A ROBINSON

REF	AREA	ITEM	CHECKED
1	TOILETS	EXTERNAL	
2		INTERNAL LADIES	
3		INTERNAL GENTS	
4		INTERNAL DISABLED	
5		ELECTRICS	
6		PATHS	
7		BOUNDARIES	
8		SIGNAGE	
9	PLAYGROUND	GATES AND FENCES	
10		HEDGES	
11		GRASS CUTTING	
12		CLIMBING FRAME	
13		SLIDE	
14		ACTIVITY CENTRE	
15		BOUNCERS	
16		ROUNABOUT	
17		SWINGS INFANT	
18		SWINGS JUNIOR	
19		FITNESS TRAIL	
20		GRASS CUTTING	
21	TENNIS COURTS	BINS	
22		SEATS	
23		SIGNS	
24		BOUNDARY FENCES	
25		GRASSED AREAS	
26		COURT SURFACE	
27		POSTS AND NETS	
28		SEATING	
29		SIGNAGE	
30	BOWLING CLUB	GREEN	
31		BUILDINGS	
32		HEDGES	
33		OTHER	
34	MOUNT FIELD	SIGNAGE	
35		FAR END FENCING	

36		NEAR END FENCING
37		OTHER BOUNDARIES
38		FOOTBALL SURFACE
39		SURROUNDING AREAS
40		BINS
41		BUILDINGS
42		RAILINGS
43		GRASS CUTTING
44		SIGNAGE
45		CAR PARK AREA
46	GOAT FIELD	PATHS AND STEPS
47		STEPS AT ENTRANCE
48		FENCES AND RAILINGS
49		BOUNDARIES/HEDGES
50		TREES
51		DOG BIN
52		SIGNAGE
53	DERI WOODS	CAR PARK AREA
54		DOG BINS
55		BOUNDARIES/HEDGES
56		TREES
57		PATHS AND STEPS
58		PUMPHOUSE
59		EQUIPMENT
60	CHAPEL OF REST	EXTERNAL
61		COOLING UNIT
62		INTERNAL
63		ELECTRICS
64		FIRE EQUIPMENT
65		GARDENS
66		GATES/BOUNDARIES
67	ST MARYS CHURCHYARD	GRASS CUTTING
68		PATHS
69		BOUNDARY WALLS
70		TREES
71		FLAG POLES
72		RAILINGS
73		SIGNAGE
74		LYCHGATE
75	ERW DDWR	GRASS CUTTING
76		HEDGES
77		RAILINGS/GATES



78		RUBBISH BIN
79		SIGNAGE
80		TREES
81		BURIAL RECORDS
82	DEFIBRILLATORS	WATERGATE STREET
83		HIGH STREET
84		MOUNT FIELD
85		BLACK LION
86		Rhiweniath village hall
87		INSTITUTE
88	TELEPHONE BOXES	WATERGATE STREET
89		HIGH STREET
90	STREET FURNITURE	BENCHES
91		BUS STOPS
92		MAP BOARDS
93		NOTICE BOARDS
94		FINGER POSTS
95		TOWN TRAIL
96		AREA NEXT TO MARKET SQUARE
97		WAR MEMORIAL
98		PARC ONNEN VERGES
99	GENERAL	OTHER ITEMS OF NOTE
100		DOCUMENTS



NOTES

Timber edging to be replaced.

Checked

Strimming required.

Two posts to be replaced.

Liners checked.

To be reviewed.

Restocked

Restocked

Riverside path repairs required

Wall next to chapel being monitored.

